

2020 AUSTRIAN GRAND PRIX

2 - 5 July 2020

From	The FIA Formula One Technical Delegate	Document	53
To	The Stewards	Date	05 July 2020
		Time	17:25

Technical Delegate's Report

Having examined car number 07 after the Race, it looks like that the loss of the RHS front wheel was caused by the wheel nut been cross threaded and therefore the wheel not been properly attached.

Jo Bauer

The FIA Formula One Technical Delegate