

2021 SAUDI ARABIAN GRAND PRIX

2 - 5 December 2021

From	The FIA Formula One Technical Delegate	Document	34
To	The Stewards	Date	05 December 2021
		Time	19:25

Technical Delegate's Report

The following parts and parameters have been replaced / changed during the Parc Fermé yesterday and today:

Mercedes:

Car 44: RHS brake caliper duct crossover scoop
 LHS brake duct blanking panel

Car 77: Front wing/nose assembly
 Fuel manifold
 Two scavenge pumps
 Two scavenge filters

Red Bull Racing Honda:

Car 33: Front wing/nose assembly
 RHS rear trackrod
 RHS rear top wishbone
 RHS rear lower wishbone
 RHS rear upright assembly
 LHS front upright gaitor
 PAS rack
 Rear brake friction material
 Parameter changes associated with RHS rear corner replacement
 Parameter changes associated with brake friction material replacement

McLaren Mercedes:

Car 03: Bib stay
Bib stay mount
Bib structure
Forward plank
Skid assemblies
Clutch IR electrical connector

Car 04: Bib cover

Alpine Renault:

Car 31: Fuel hatch cover livelock fastener

Ferrari:

Car 55: RHS rear wing endplate

AlphaTauri Honda:

Car 22: Rear brake friction material
Parameter changes associated with brake friction material replacement

Car 10: LHS and RHS rear view mirror assemblies
AOT line O-ring

Haas Ferrari:

Car 47: Anchor nut on RHS floor section

Williams Mercedes:

Car 06: LHS and RHS threaded floor inserts

All above parts have been replaced with the approval of the FIA technical delegate following a written request from the team concerned, this being in accordance with Article 34.2 of the 2021 Formula One Sporting Regulations.

Jo Bauer

The FIA Formula One Technical Delegate